

Date of Recall submission: **26-Jul-26**

Vehicles Affected:

Make	Model	Model Year
ARBOC	SPIRIT OF INDEPENDENCE	2017-2020
ARBOC	SPIRIT OF INDEPENDENCE	2024
ARBOC	SPIRIT OF INDEPENDENCE	2026

Internal Reference Number: **N/A**

Transport Canada Recall No.: **2026-363**

Defect or Noncompliance Description: An incorrect sized washer diameter may have been installed during production on rear leaf-spring hanger bolts.

Safety Risk / Result: With incorrect sized washers, this may cause rear spring to become disconnected from the frame, increasing the risk of a crash.

Remedy Description: The remedy is removing the existing bolt/washers and replacing the washers with a larger outer diameter washer

Precautions prior to remedy, if any: Operators should pay attention to noises from the rear of the vehicle or poor handling.

Remedy Material Availability: The remedy is available

Costs: ARBOC will cover the cost of material and labour. Recall notifications are planned to be sent on or before 18-Sep-2026, giving instructions on how to have the remedy applied.

Questions: If you have any questions about a **specific vehicle, a recall number, or to report a safety concern**, please send the request to: safetyrecalls@nfigroup.com
In the subject line, please indicate, as applicable:
-"RECALL INFORMATION - VIN 12345678X87654321", with the Transport Canada recall number YYYY-123 (in the yellow highlighted cell on this page), OR
-"VEHICLE INFORMATION - VIN 12345678X87654321" OR
-"SAFETY QUESTION/ISSUE - VIN 12345678X87654321", OR
-"ADDRESS CHANGE - VIN 12345678X87654321"
If known, please provide the SR and fleet number of the specific vehicle, and any pertinent information to assist in getting a response to you.

Website document last updated: **04-Aug-26**