

Date of Recall submission: **19-Dec-25**

Vehicles Affected:

Make	Model	Model Year
New Flyer	XD40	2020
New Flyer	XD40	2025-2026
New Flyer	XDE40	2026
New Flyer	XE35	2017
New Flyer	XE40	2013
New Flyer	XE40	2019-2026
New Flyer	XE60	2017
New Flyer	XE60	2024-2025
New Flyer	XHE40	2022
New Flyer	XHE40	2024
New Flyer	XHE60	2024

Internal Reference Number: **N/A**

Transport Canada Recall No.: **2025-711**

Defect or Noncompliance Description:

When the ABS (anti-lock brake) control module loses power or communication, the ABS dash lamp does not illuminate on certain buses, which is noncompliant to TSD 121, S5.1.6.2 Antilock Malfunction Signal

Safety Risk / Result:

A non-functioning ABS system (due to loss of power or communication) increases the risk of a crash.

Remedy Description:

New Flyer will release new software that provides a "heartbeat" signal to the affected module. If no communication is detected, the ABS lamp will illuminate steady on the dash and remain steady when the ignition is "ON". New Flyer will arrange to send this software to customers for uploading or make arrangements with customers for New Flyer personnel to upload.

Precautions prior to remedy, if any:

If the system has proper communication/connection, the ABS lamp will illuminate momentarily during the initial ignition on / start-up sequence.

Remedy Material Availability:

Software updates are being released and should be available for customers in January-2026.

Costs:

New Flyer will provide this software at no cost to owners, and reimburse owners for the programming through our normal warranty process.

Questions:

If you have any questions about a **specific vehicle, a recall number, or to report a safety concern**, please send the request to: safetyrecalls@nfigroup.com

In the subject line, please indicate, as applicable:
 -"RECALL INFORMATION - VIN 12345678X87654321", with the Transport Canada recall number YYYY-123 (in the yellow highlighted cell on this page), OR
 -"VEHICLE INFORMATION - VIN 12345678X87654321" OR
 -"SAFETY QUESTION/ISSUE - VIN 12345678X87654321", OR
 -"ADDRESS CHANGE - VIN 12345678X87654321"

If known, please provide the SR and fleet number of the specific vehicle, and any pertinent information to assist in getting a response to you.

Website document last updated: **22-Dec-25**